

Vehicle registration

AUF267K - 1972 FIAT, NOT RECORDED



Make **FIAT**

Model

NOT RECORDED

VRM AUF267K Full VIN 110F6131175

Year manufacture

Gearbox type

Engine number U860055528066

First registered 17/04/2007

Gearbox UNKNOWN

Engine capacity 499cc

Kerb weight kg

Exported NO

Euro status

First registered UK 17/04/2007

Forward gears 0 gears

Door plan SALOON

Date exported

Driven Axle

VIN last 5 31175

Not exported

Seating capacity 4 seats

1972

Scrapped NO

Imported NO

Type approval

CO2 g/km

PETROL

Colour

RED

Fuel

Date scrapped Not scrapped Imported Non EU

NO

Vehicle Class Car

SMMT details

AUF267K - 1972 FIAT, NOT RECORDED

SMMT Marque

SMMT Range

Model Variant

FIAT

Series

Gearbox

No of Gears

Country of origin

Fuel

Engine size

Body

No of doors Unknown

Model start date

System setup date

Termination date Current model

Drive type

Vehicle registration

AUF267K - 1972 FIAT, NOT RECORDED

Total keepers

Previous VRMs

Colour changes

V5 certificates

https://panel.ukvehicledata.co.uk/Weblookup

Techical data

AUF267K - 1972 FIAT, NOT RECORDED

Weights & Dimensions			Performance			
Kerb weight	Gross weight kg	<u>Length</u> mm	<u>Height</u> mm	Power Bhp	Power Kw	Peak power rpm
		Width mm	Boot capacity	Torque FtLb	<u>Torque Nm</u>	<u>Peak Torque</u> rpm
Fuel capacity				Max speed mph	Max speed kph	
Engine techni	ical					
Engine code Not enabled Engine manuf	- acturer					
Cylinders	<u>Valves/cyl</u>	Stroke mm	Bore mm			
Arrangement	Cam type	Engine location	<u>Aspiration</u>			

Vehicle coding

AUF267K - 1972 FIAT, NOT RECORDED

UKVD ID DVLA code MVRIS code Fleetnet code No match ABI Code Glass ID ACRISS code Tecdoc KType License required License required License required License required Engine code Not enabled

MOT Overview

AUF 267K - FIAT, NOT RECORDED



MOT Expired

Next required: 01/10/2021 Days remaining: 0 Pass certificates: 12 Fail certificates: 8


> Total days without an MOT: 960 Mileage clocking detected: Yes Mileage records held: 20

Mileage records AUF 267K - FIAT, NOT RECORDED

We hold 20 MOT mileage records from 2,734 to 34,951 miles between 28/03/07 and 02/10/20 for AUF 267K.

• We may have detected mileage clocking issues around 34,353 miles, please check the data carefully.


Date	Mileage
02/10/2020	34,951
19/09/2018	34,778
03/10/2017	34,493
28/09/2017	21,430
12/05/2016	34,353
15/04/2015	33,757
10/04/2015	33,743
15/05/2014	30,677
18/04/2013	27,272
16/04/2013	27,272
01/06/2011	22,652
27/05/2011	22,641
06/05/2010	12,188
06/05/2010	19,605
12/05/2009	12,967
11/05/2009	12,955
08/04/2008	7,698
02/04/2008	7,687
10/04/2007	2,740
28/03/2007	2,734



MOT Certificates

AUF 267K - FIAT, NOT RECORDED

PASS: 2nd October 2020 AUF 267K - FIAT, NOT RECORDED, PETROL NEXT MOT DUE: 01/10/2021 DAYS WITHOUT MOT: 379
Test date: 02/10/2020 Test id: 6026-0911-8023 Result: PASS
Mileage reading 34,951 Odometer units Miles Expiry date 01/10/2021
Advisories No advisories



PASS: 3rd October 2017

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021 DAYS WITHOUT MOT: 144

Test date: 03/10/2017 **Test id:** 8810-2240-8737

Result: PASS

Re-test of 7286 2377 3234

Mileage reading

34,493

Odometer units

Miles

Expiry date

02/10/2018

Advisories

steering idler has slight play in bushes

Suspension spring mounting prescribed area is corroded but not considered excessive front leaf spring area on NS (2.4.A.3)

Front Axle king pin has slight play in pin and/or bush both sides (2.5.A.3a)

Advisory annotation items

1: Advisory steering idler has slight play in bushes

2: Advisory Suspension spring mounting prescribed area is corroded but not considered excessive front leaf spring area

on NS (2.4.A.3)

3: Advisory Front Axle king pin has slight play in pin and/or bush both sides (2.5.A.3a)

FAIL: 28th September 2017

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021

Test date: 28/09/2017
Test id: 7286-2377-3234
Result: FAIL

Mileage reading

21,430

Odometer units

Kilometers

Expiry date

Failed

Failure list

- 1: Nearside Rear Direction indicator not working (1.4.A.2c)
- 2: Nearside Rear position lamp(s) not working (1.1.A.3b)
- 3: Offside Headlamp not working on dipped beam (1.7.5a)
- 4: Nearside Headlamp not working on main beam (1.7.5a)
- 5: Offside Rear Suspension arm corroded and seriously weakened (2.4.G.1)
- 6: Offside Rear Suspension arm cracked (2.4.G.1)

Advisories

steering idler has slight play in bushes

Suspension spring mounting prescribed area is corroded but not considered excessive front leaf spring area on NS (2.4.A.3)

Front Axle king pin has slight play in pin and/or bush both sides (2.5.A.3a)

Advisory annotation items

- 1: Fail Nearside Rear Direction indicator not working (1.4.A.2c)
- : Fail Nearside Rear position lamp(s) not working (1.1.A.3b)
- 3: Fail Offside Headlamp not working on dipped beam (1.7.5a)
- 4: Fail Nearside Headlamp not working on main beam (1.7.5a)
- 5: Advisory steering idler has slight play in bushes
- : Advisory Suspension spring mounting prescribed area is corroded but not considered excessive front leaf spring area

on NS (2.4.A.3)

- 7: Advisory Front Axle king pin has slight play in pin and/or bush both sides (2.5.A.3a)
- 8: Fail Offside Rear Suspension arm corroded and seriously weakened (2.4.G.1)
- 9: Fail Offside Rear Suspension arm cracked (2.4.G.1)

PASS: 12th May 2016

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021 DAYS WITHOUT MOT: 28

Test date: 12/05/2016
Test id: 9166-3261-6631
Result: PASS

Mileage reading

34,353

Odometer units

Miles

Expiry date

14/05/2017

Advisories

Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)

Advisory annotation items

1: Advisory Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

2: Advisory Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)

PASS: 15th April 2015

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021 DAYS WITHOUT MOT: 0

Test date: 15/04/2015 **Test id:** 4178-6580-5105

Result: PASS

Re-test of 2169 7090 5173

Mileage reading

33,757

Odometer units

Miles

Expiry date

14/05/2016

Advisories

Offside Front Axle king pin has slight play in pin and/or bush (2.5.A.3a)

Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Vehicle structure has slight corrosion (6.1.B.2)

Brake pipe slightly corroded (3.6.B.2c)

slight play in steering,

oil leak

n/s rear tyre starting to wear on edge,

Advisory annotation items

- 1: Advisory Offside Front Axle king pin has slight play in pin and/or bush (2.5.A.3a)
- 2: Advisory Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- 3: Advisory Vehicle structure has slight corrosion (6.1.B.2)
- 4: Advisory Brake pipe slightly corroded (3.6.B.2c)
- 5: USER ENTERED slight play in steering,
- 6: USER ENTERED oil leak
- 7: USER ENTERED n/s rear tyre starting to wear on edge,

FAIL: 10th April 2015

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021

Test date: 10/04/2015
Test id: 2169-7090-5173
Result: FAIL

Mileage reading

33,743

Odometer units

Miles

Expiry date

Failed

Failure list

- 1: Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- 2: Offside Front Side repeater not working (1.4.A.2c)
- 3: Indicator tell tale inoperative (1.4.A.2a)
- 4: Front Windscreen washer provides insufficient washer liquid (8.2.3)
- 5: Brake pipe inadequately supported (3.6.B.1)
- 6: Nearside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)
- 7: Nearside Front Axle king pin has excessive play in pin and/or bush adversely affecting the steering (2.5.A.3a)
- 8: Nearside Front Front wheel bearing rough when rotated (2.5.A.2)
- 9: Offside Front Front wheel bearing rough when rotated (2.5.A.2)
- 10: Offside Rear Drive shaft which forms part of the suspension support bearing excessively worn (2.4.G.4d)

Advisories

Offside Front Axle king pin has slight play in pin and/or bush (2.5.A.3a)

Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Vehicle structure has slight corrosion (6.1.B.2)

Brake pipe slightly corroded (3.6.B.2c)

slight play in steering,

oil leak

n/s rear tyre starting to wear on edge,

Advisory annotation items

1:	Fail	Front Headlamp aim beam image obviously incorrect (1.8.A.1b)	

- 2: Fail Offside Front Side repeater not working (1.4.A.2c)
- 3: Fail Indicator tell tale inoperative (1.4.A.2a)
- 4: Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)
- 5: Fail Brake pipe inadequately supported (3.6.B.1)
- 6: Fail Nearside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the

ingress of dirt (2.2.C.1c)

7: Fail Nearside Front Axle king pin has excessive play in pin and/or bush adversely affecting the steering (2.5.A.3a)

8: Fail Nearside Front Front wheel bearing rough when rotated (2.5.A.2)

9:	Fail	Offside Front Front wheel bearing rough when rotated (2.5.A.2)	
10:	Fail	Offside Rear Drive shaft which forms part of the suspension support bearing excessively worn (2.4.G.4d)	
11:	Advisory	Offside Front Axle king pin has slight play in pin and/or bush (2.5.A.3a)	
12:	Advisory	Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
13:	Advisory	Vehicle structure has slight corrosion (6.1.B.2)	
14:	Advisory	Brake pipe slightly corroded (3.6.B.2c)	
15: L	JSER ENTERE	D slight play in steering,	
16: USER ENTERED oil leak			
17: USER ENTERED n/s rear tyre starting to wear on edge,			

PASS: 15th May 2014

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021 DAYS WITHOUT MOT: 27

> **Test date:** 15/05/2014 **Test id:** 3164-6513-4140 **Result:** PASS

Mileage reading

30,677

Odometer units

Miles

Expiry date

14/05/2015

Advisories

Vehicle structure has slight corrosion (6.1.B.2)

Brake pipe slightly corroded (3.6.B.2c)

Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Advisory annotation items

- 1: Advisory Vehicle structure has slight corrosion (6.1.B.2)
- 2: Advisory Brake pipe slightly corroded (3.6.B.2c)
- 3: Advisory Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- 4: Advisory Parking brake: parking brake efficiency only just met. It would appear that the braking system requires

adjustment or repair. (3.7.B.7)

PASS: 18th April 2013

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021 DAYS WITHOUT MOT: 322

Test date: 18/04/2013 **Test id:** 7196-8860-3178

Result: PASS

Re-test of 7470 1690 3113

Mileage reading

27,272

Odometer units

Miles

Expiry date

17/04/2014

Advisories

Vehicle structure has slight corrosion (6.1.B.2)

Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

oil leak

Advisory annotation items

1: Advisory Vehicle structure has slight corrosion (6.1.B.2)

2: Advisory Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

3: USER ENTERED oil leak

FAIL: 16th April 2013

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021

Test date: 16/04/2013
Test id: 7470-1690-3113
Result: FAIL

Mileage reading

27,272

Odometer units

Miles

Expiry date

Failed

Failure list

- 1: Offside Front position lamp(s) not working (1.1.A.3b)
- 2: Nearside Headlamp not working on main beam (1.7.5a)
- 3: Offside Front Headlamp aim too low (1.8)
- 4: Offside Headlamp aim beam image kick up to the offside (1.8)
- 5: Nearside Headlamp aim too high (1.8)
- 6: Nearside Indicator tell tale inoperative (1.4.A.2a)
- 7: Offside Indicator tell tale inoperative (1.4.A.2a)
- 8: Nearside Rear position lamp(s) not working (1.1.A.3b)
- 9: Nearside Rear Stop lamp not working (1.2.1b)
- 10: Exhaust has a major leak of exhaust gases (7.1.2)
- 11: Nearside Rear wheel bearing rough when rotated (2.6.1)

Advisories

Vehicle structure has slight corrosion (6.1.B.2)

Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

oil leak

Advisory annotation items

- 1: Fail Offside Front position lamp(s) not working (1.1.A.3b)
- 2: Fail Nearside Headlamp not working on main beam (1.7.5a)
- 3: Fail Offside Front Headlamp aim too low (1.8)
- 4: Fail Offside Headlamp aim beam image kick up to the offside (1.8)
- 5: Fail Nearside Headlamp aim too high (1.8)
- 6: Fail Nearside Indicator tell tale inoperative (1.4.A.2a)
- 7: Fail Offside Indicator tell tale inoperative (1.4.A.2a)
- 8: Fail Nearside Rear position lamp(s) not working (1.1.A.3b)
- 9: Fail Nearside Rear Stop lamp not working (1.2.1b)
- 10: Fail Exhaust has a major leak of exhaust gases (7.1.2)
- 11: Fail Nearside Rear wheel bearing rough when rotated (2.6.1)
- 2: Advisory Vehicle structure has slight corrosion (6.1.B.2)
- 13: Advisory Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

14: USER ENTERED oil leak

PASS: 1st June 2011

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021 DAYS WITHOUT MOT: 26

Test date: 01/06/2011 **Test id:** 9487-6245-1116

Result: PASS

Re-test of 9450 0714 1175

Mileage reading

22,652

Odometer units

Miles

Expiry date

31/05/2012

Advisories

Brake pipe slightly corroded (3.6.B.2c)

Vehicle structure has slight corrosion (6.1.B.2)

Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

oil leak

slight play in front hubs....

Advisory annotation items

1: Advisory Brake pipe slightly corroded (3.6.B.2c)

2: Advisory Vehicle structure has slight corrosion (6.1.B.2)

3: Advisory Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

4: USER ENTERED oil leak

5: USER ENTERED slight play in front hubs....

FAIL: 27th May 2011

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021

Test date: 27/05/2011
Test id: 9450-0714-1175
Result: FAIL

Mileage reading

22,641

Odometer units

Miles

Expiry date

Failed

Failure list

- 1: Offside Rear Direction indicators not working (1.4.A.2c)
- 2: Offside Front Side repeater not working (1.4.A.2c)
- 3: Offside Rear Suspension arm corroded and seriously weakened (2.4.G.1)
- 4: Nearside Front wheel bearing rough when rotated (2.5.A.2)

Advisories

Brake pipe slightly corroded (3.6.B.2c)

Vehicle structure has slight corrosion (6.1.B.2)

Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

oil leak

slight play in front hubs....

Advisory annotation items

- 1: Fail Offside Rear Direction indicators not working (1.4.A.2c)
- Fail Offside Front Side repeater not working (1.4.A.2c)
- 3: Fail Offside Rear Suspension arm corroded and seriously weakened (2.4.G.1)
- 4: Fail Nearside Front wheel bearing rough when rotated (2.5.A.2)
- 5: Advisory Brake pipe slightly corroded (3.6.B.2c)
- : Advisory Vehicle structure has slight corrosion (6.1.B.2)
- Advisory Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- 8: USER ENTERED oil leak
- 9: USER ENTERED slight play in front hubs....

PASS: 6th May 2010 AUF 267K - FIAT, NOT RECORDED, PETROL **NEXT MOT DUE: 01/10/2021** DAYS WITHOUT MOT: 0 **Test date:** 06/05/2010 **Test id:** 5235-8682-0153 Result: PASS Re-test of 4530 3672 0132 Mileage reading 12,188 **Odometer units** Kilometers **Expiry date** 11/05/2011 Advisories Vehicle structure has slight corrosion (6.1.B.2) oil leak Advisory annotation items 1: Advisory Vehicle structure has slight corrosion (6.1.B.2) 2: USER ENTERED oil leak

FAIL: 6th May 2010

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021

Test date: 06/05/2010
Test id: 4530-3672-0132
Result: FAIL

Mileage reading

19,605

Odometer units

Miles

Expiry date

Failed

Failure list

- 1: Driver's seat cannot be secured in the upright position. (6.2.A.2)
- 2: Nearside rear parking brake recording little or no effort (3.7.B.6a)
- 3: Offside rear parking brake recording little or no effort (3.7.B.6a)
- 4: Nearside Front Headlamp aim beam image kick up to the offside (1.8)
- 5: Offside Front Headlamp aim beam image kick up to the offside (1.8)
- 6: Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- 7: Parking brake: efficiency below requirements (3.7.B.7)

Advisories

Vehicle structure has slight corrosion (6.1.B.2)

oil leak

Advisory annotation items

- 1: Fail Driver's seat cannot be secured in the upright position. (6.2.A.2)
- : Fail Nearside rear parking brake recording little or no effort (3.7.B.6a)
- 3: Fail Offside rear parking brake recording little or no effort (3.7.B.6a)
- 4: Fail Nearside Front Headlamp aim beam image kick up to the offside (1.8)
- 5: Fail Offside Front Headlamp aim beam image kick up to the offside (1.8)
- 6: Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- 7: Fail Parking brake: efficiency below requirements (3.7.B.7)
- 8: Advisory Vehicle structure has slight corrosion (6.1.B.2)
- 9: USER ENTERED oil leak

PASS: 12th May 2009

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021 DAYS WITHOUT MOT: 34

Test date: 12/05/2009 **Test id:** 1812-9213-9136

Result: PASS

Re-test of 9608 4143 9103

Mileage reading

12,967

Odometer units

Miles

Expiry date

11/05/2010

Advisories

Vehicle structure has slight corrosion (6.1.B.2)

Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

rear tyres perrished and low on tread

slight play in steering

oil leak

Advisory annotation items

1: Advisory Vehicle structure has slight corrosion (6.1.B.2)

2: Advisory Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

3: USER ENTERED rear tyres perrished and low on tread

4: USER ENTERED slight play in steering

5: USER ENTERED oil leak

FAIL: 11th May 2009

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021

Test date: 11/05/2009
Test id: 9608-4143-9103
Result: FAIL

Mileage reading

12,955

Odometer units

Miles

Expiry date

Failed

Failure list

1: Offside Front wheel bearing rough when rotated (2.5.A.2)

Advisories

Vehicle structure has slight corrosion (6.1.B.2)

Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

rear tyres perrished and low on tread

slight play in steering

oil leak

Advisory annotation items

1: Fail Offside Front wheel bearing rough when rotated (2.5.A.2)

2: Advisory Vehicle structure has slight corrosion (6.1.B.2)

3: Advisory Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

4: USER ENTERED rear tyres perrished and low on tread

5: USER ENTERED slight play in steering

6: USER ENTERED oil leak

PASS: 8th April 2008

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021 DAYS WITHOUT MOT: 0

> **Test date:** 08/04/2008 **Test id:** 7118-9959-8050

> > Result: PASS

Re-test of 9342 5339 8059

Mileage reading

7,698

Odometer units

Miles

Expiry date

09/04/2009

Advisories

Brake pipe slightly corroded (3.6.B.2c)

tyres perrished

sus, bushs perrished

slight play in hubs

Advisory annotation items

1: Advisory Brake pipe slightly corroded (3.6.B.2c)

2: USER ENTERED tyres perrished

3: USER ENTERED sus, bushs perrished

4: USER ENTERED slight play in hubs

FAIL: 2nd April 2008

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021

Test date: 02/04/2008
Test id: 9342-5339-8059
Result: FAIL

Mileage reading

7,687

Odometer units

Miles

Expiry date

Failed

Failure list

- 1: Nearside Front Headlamp not working on dipped beam (1.7.5a)
- 2: Nearside Headlamp aim not tested (1.8.A.1c)
- 3: Nearside Front Side repeater not working (1.4.A.2c)
- 4: Nearside Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)
- 5: Nearside Front wheel bearing rough when rotated (2.5.A.2)
- 6: Offside Rear wheel bearing rough when rotated (2.6.1)

Advisories

Brake pipe slightly corroded (3.6.B.2c)

tyres perrished

sus, bushs perrished

slight play in hubs

Advisory annotation items

- 1: Fail Nearside Front Headlamp not working on dipped beam (1.7.5a)
- 2: Fail Nearside Headlamp aim not tested (1.8.A.1c)
- 3: Fail Nearside Front Side repeater not working (1.4.A.2c)
- 4: Fail Nearside Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance

(1.1.A.3d)

- 5: Fail Nearside Front wheel bearing rough when rotated (2.5.A.2)
- 6: Fail Offside Rear wheel bearing rough when rotated (2.6.1)
- 7: Advisory Brake pipe slightly corroded (3.6.B.2c)
- 8: USER ENTERED tyres perrished
- 9: USER ENTERED sus, bushs perrished
- 10: USER ENTERED slight play in hubs

PASS: 10th April 2007

AUF 267K - FIAT, NOT RECORDED, PETROL **NEXT MOT DUE: 01/10/2021** DAYS WITHOUT MOT: Test date: 10/04/2007 **Test id:** 2341-7000-7141 Result: PASS Re-test of 5814 8728 7062 Mileage reading 2,740 **Odometer units** Kilometers **Expiry date** 09/04/2008 Advisories Headlamp masks/converters fitted Advisory annotation items 1: USER ENTERED Headlamp masks/converters fitted

FAIL: 28th March 2007

AUF 267K - FIAT, NOT RECORDED, PETROL

NEXT MOT DUE: 01/10/2021

Test date: 28/03/2007 Test id: 5814-8728-7062 Result: FAIL

Mileage reading

2,734

Odometer units

Kilometers

Expiry date

Failed

Failure list

- 1: Statutory seat belt missing (5.1.1)
- 2: Windscreen washer control missing (8.2.1a)
- 3: Front position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)
- 4: Offside Headlamp not working on dipped beam (1.7.5a)
- 5: Offside Headlamp not working on main beam (1.7.5a)
- 6: Nearside Headlamp aim too high (1.8)
- 7: Nearside Headlamp not in good working order adversely affecting beam image (1.2.4a)
- 8: Registration plate lamp not working (1.1.5c)
- 9: Offside Stop lamp adversely affected by the operation of another lamp (1.2.1f)
- 10: Nearside Front Direction indicator incorrect colour (1.4.A.2f)
- 11: Offside Front Direction indicator incorrect colour (1.4.A.2f)
- 12: Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)
- 13: Offside Headlamp aim not tested (1.8.A.1c)

Advisories

No advisories

Advisory annotation items

1: Statutory seat belt missing (5.1.1) Fail Windscreen washer control missing (8.2.1a) Front position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f) 3: 4: Offside Headlamp not working on dipped beam (1.7.5a) Offside Headlamp not working on main beam (1.7.5a) Nearside Headlamp aim too high (1.8) Fail 7: Nearside Headlamp not in good working order adversely affecting beam image (1.2.4a) Registration plate lamp not working (1.1.5c) 8: Fail

- 9: Offside Stop lamp adversely affected by the operation of another lamp (1.2.1f)
- 10: Nearside Front Direction indicator incorrect colour (1.4.A.2f)
- 11: Offside Front Direction indicator incorrect colour (1.4.A.2f)
- Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

13: Fail Offside Headlamp aim not tested (1.8.A.1c)