

Porsche 911

VIN: **WP0ZZZ99ZVS312492**

Petrol

1997

Generated on **2023-10-17 10:20**



Theft



Odometer



**Financial and legal
status**



Damage



Things to know about Porsche 911 1997

 AI generated

The 1997 Porsche 911 is a classic sports car that comes in a variety of body types and engine configurations. One of the standout features of the 911 is its ability to blend high performance with comfort and luxury.

There are a number of engines available for the 1997 Porsche 911, including a 3.6-liter flat-six that produces 282 horsepower and 250 lb-ft of torque. This engine comes paired with a six-speed manual or a four-speed automatic transmission. Another engine option is the 3.6-liter turbocharged flat-six that produces 408 horsepower and 398 lb-ft of torque. This engine is paired with a six-speed manual transmission only.

When it comes to body types, the 1997 Porsche 911 is available as a coupe, cabriolet, and Targa. The coupe and cabriolet offer a more traditional sports car look, while the Targa has a unique removable roof panel that provides the best of both worlds. All three body types offer the same engine options.

Other notable specs of the 1997 Porsche 911 include a top speed of 168 mph, a 0-60 time of 4.6 seconds, and a fuel economy rating of 16 mpg in the city and 23 mpg on the highway. Standard features of the 911 include leather seats, a power sunroof, air conditioning, and an AM/FM stereo with a CD player.

Overall, the 1997 Porsche 911 is a high-performance sports car that offers a range of engine options and body types to suit different driving styles and preferences. With its sleek design, luxurious amenities, and impressive performance capabilities, the 911 is a timeless classic that continues to impress car enthusiasts to this day.

This description is AI-generated and has not undergone human review for potential inaccuracies.



+31

Data sources

We checked 900+ data sources in **35 countries**



Driver & Vehicle Licensing Agency



Driver & Vehicle Standards Agency

Partners

Fuelling this report

Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?



We didn't find any records that the vehicle was stolen.

Here's what we checked:



Currently wanted as stolen

✓ No record found



Stolen in the past

✓ No record found

Current status unknown



Stolen in the past

✓ No record found

Vehicle has been recovered

Police database stolen vehicle **check completed in:**



United Kingdom



Slovakia



Sweden



Romania



Czechia



Canada

Odometer


Are there signs of mileage roll backs or discrepancies?



Last known mileage: 89,953 mi



17 mileage records found



Odometer records

1997-01	6 mi
2006-02	75,890 mi
2007-03	78,985 mi
2008-07	79,660 mi
2008-07	79,662 mi
2009-07	80,994 mi
2011-02	81,477 mi
2012-03	82,491 mi
2013-10	83,182 mi

Odometer records

2015-06	85,440 mi
2016-06	86,317 mi
2017-06	86,439 mi
2018-06	86,786 mi
2019-05	87,948 mi
2021-07	89,271 mi
2022-07	89,658 mi
2023-06	89,953 mi

Financial and legal status

Has the vehicle passed its technical inspections? Does it have property rights restrictions or outstanding loans?



Tech inspection is valid **United Kingdom**

Legal



MOT (technical inspection)

Passed 2023-06

United Kingdom

Has successfully passed technical inspection
Valid until 2024-07



Scrap

✓ No record found

No record that vehicle was marked as scrapped



Exported

✓ No record found

No export records found



Imported

✓ No record found

No import records found

Outstanding finance



Lease

✓ No record found

No data available on outstanding loan or finance agreement



Operating-lease

✓ No record found

No record of vehicle being on an operating-lease



Unit-stocking

✓ No record found

No record of vehicle being under unit-stocking finance

Damage

Has this vehicle been damaged in the past? What was the value of the damages?



No damage records found

Damage records



Occasional inaccuracies can occur, especially when checking older vehicles. Illegitimate mechanical garages may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Specs

What specs and equipment are on record for this vehicle?



Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications



Make
Porsche



Model
911



Variant
**911 Carrera S
Cabriolet**



Manufacture year
1997



Fuel type
Petrol



Gearbox type
Manual

Timeline

25 records found

The timeline of records for this vehicle

Latest records

1997-01

 **Country unknown**



Was manufactured

The country indicates either the location of manufacturing facility, assembly plant or registration address of the manufacturer. The date may be approximate.

1997-01

 **United Kingdom**



Was registered

The record represents an administrative event. This could be related to a change of ownership, documents, etc

2006-02

 **United Kingdom**



Failed a technical inspection

A failed technical inspection (MOT) was recorded in the indicated country. Unsuccessful emission tests will also fall under the same category.

- Lower Windscreen wiper blade deteriorated (8.2.2)
- front & rear brake disc inner faces becoming †corroded/pitted. †

2006-02

 **United Kingdom**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2007-03

 **United Kingdom**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2008-07



Failed a technical inspection

A failed technical inspection (MOT) was recorded in the indicated country. Unsuccessful emission tests will also fall under the same category.

- Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Offside Front brake disc slightly pitted (3.5.1h)
- Offside Rear brake disc slightly pitted (3.5.1h)
- Nearside Front brake disc slightly pitted (3.5.1h)
- Nearside Rear brake disc slightly pitted (3.5.1h)

2008-07



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2009-07



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2011-02



Failed a technical inspection

A failed technical inspection (MOT) was recorded in the indicated country. Unsuccessful emission tests will also fall under the same category.

- front brake discs pitted/corroded
- Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

2011-02



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2012-03



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2013-10



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2015-06



Failed a technical inspection

A failed technical inspection (MOT) was recorded in the indicated country. Unsuccessful emission tests will also fall under the same category.

- n/s/f sidelight lense has hole in it
- Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- oil residue underside of engine

2015-06



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2015-07



Ownership changed

The country indicated the geographical location of a documented ownership change or renewal. Please note that some changes may be formal, e.g., end-of-lease transfers and similar.

2016-06



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2017-06

 **United Kingdom**



Failed a technical inspection

A failed technical inspection (MOT) was recorded in the indicated country. Unsuccessful emission tests will also fall under the same category.

- Offside Front position lamp(s) not working (1.1.A.3b)
- Rear fog lamp not working (1.3.2b)
- Offside Rear position lamp(s) not working (1.1.A.3b)
- Nearside Stop lamp not working (1.2.1b)

2017-06

 **United Kingdom**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2018-06

 **United Kingdom**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2019-05

 **United Kingdom**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2021-07

 **United Kingdom**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2021-07

 **United Kingdom**



Ownership changed

The country indicated the geographical location of a documented ownership change or renewal. Please note that some changes may be formal, e.g., end-of-lease transfers and similar.

2022-07

 **United Kingdom**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2023-06

 **United Kingdom**



Failed a technical inspection

A failed technical inspection (MOT) was recorded in the indicated country. Unsuccessful emission tests will also fall under the same category.

- Offside Front Position lamp not working (4.2.1 (a) (ii))
- Offside Front Headlamp aim too high (4.1.2 (a))
- Offside Rear Position lamp not working (4.2.1 (a) (ii))

2023-06

 **United Kingdom**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.



+31

Data sources

We checked 900+ data sources in **35 countries**



Driver & Vehicle Licensing Agency



Driver & Vehicle Standards Agency

Partners

Fuelling this report